

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

09747648-122600



009227-349260





FIG 2





FIG 3


FIG 2C WITH INVENTION-TOPVIEW
 -VERT. I-BEAM CENTER SECTION
 PERPENDICULAR TO
 PROPOSED CURTAIN WALL-

009747648-122600





BRACKET PLATE

FIG 4



09742648-122500





FLAT SLATE FOR FIRST
SECOND MODE OF ACTION
(SIDE VIEW)

09747648-123600




FIGURE 8
TOP VIEW - "L-FOLD"




FIGURE 9
TOP VIEW "C-FOLD"

09747648-122500




FIGURE 10A

09747648-123600




FIGURE 10B